

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) / Import Vehicles

CAMPAIGN No.	4726	DATE	April,13,2020
MANUFACTURER	HITACHI CONSTRUCTION MACHINERY CO.,LTD (JAPAN)		
DESCRIPTION OF DEFECT	<p>Some hydraulic pumps for moving tire rollers have improperly machined internal components. As a result, the wear of the parts tends to progress, and the parts may fall off due to excessive wear. In the worst case, the dropped parts may damage the internal mechanism, prevent the parking brake from being released, and make it impossible to drive.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF	REMARKS
KDP-CP220	「CP220-3」	2012~2014	165	
KDP-N22A2	「HN220WHH-2」	2013~2014	13	
WDP-TAB	「ZC220P-5」	2014~2017	64	
WDP-N22A2	「HN220WHH-3」	2014	10	
4 models in total	4 models in total	2012~2017	Total 252	