

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3021	DATE	April 13th, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The ISOFIX child seat mounting brackets on affected vehicles may not have the required durability. When using child seats with ISOFIX mounting and additional support on the vehicle floor, one or more brackets can break under increased dynamic bending load over lifetime. With a broken retaining bracket, the mounting of an ISOFIX child seat is no longer possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-KU30S	BMW X6 xDrive 35i	2014 - 2019	181
DBA-KU30		2014 - 2019	1,125
CBA-KU44	BMW X6 xDrive 50i	2014 - 2019	173
CBA-KU44S		2014 - 2018	36
ABA-KT44	BMW X6M	2014 - 2019	209
		TOTAL	1,724