

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3023	DATE	April 13th, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During deployment the driver airbag could become damaged by the airbag cover. If the airbag gets damaged, this would lead to an inadequately inflation and an impaired restraint effect. Furthermore the driver would be exposed to an output flow of hot gas of the airbag inflator.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-7K15	BMW 118i	2020	3
	BMW 218i Gran Coupe		2
		TOTAL	5