

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Imported Vehicles

CAMPAIGN No.	gai-3010	DATE	April 15 , 2020
MANUFACTURER	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	Since Fixing nuts of Bonnet Lock may not be tightened enough to the specific tightening torque value, the fixing nuts may be loosen due to some vehicle vibration while driving. At the worst case, the bonnet may open while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-DFM5P	ALPINE A110	2018 - 2019	340
		TOTAL	340