

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4732	DATE	April 22, 2020
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	In some detachable container vehicles, the fuse are not installed because of an inadequate drawing instructions for the power circuit of the electrically-operated retractable rear bumper. Therefore, over-current flows when the wire is short-circuited, and in the worst case, the wire coating may melt and cause smoke or fire.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	2KG-FS1EJA	HINO PROFIA	2018	1
	2PG-FR1AJA	HINO PROFIA	2018-2019	3
	2PG-FS1AJA	HINO PROFIA	2018-2019	11
	QKG-FR1EPBA	HINO PROFIA	2013-2014	2
	QKG-FS1ARBA	HINO PROFIA	2014	1
	QKG-FS1ERBA	HINO PROFIA	2013-2014	4
	QKG-FS1EREA	HINO PROFIA	2015	2
	QPG-FR1EPEA	HINO PROFIA	2015-2016	2
	QPG-FS1EPEA	HINO PROFIA	2015	1
	QPG-FS1EREA	HINO PROFIA	2014-2017	29
ISUZU	2PG-CYM77CM	GIGA	2019	1
	2PG-CYZ77CM	GIGA	2018-2019	10
	LKG-CYZ77AM	GIGA	2014	1
	QKG-CYM77AM	GIGA	2014-2015	3
	QKG-CYM77BM	GIGA	2016	1
	QKG-CYZ77AM	GIGA	2013-2015	11
	QKG-CYZ77BM	GIGA	2016-2018	14
MITSUBISHI	2PG-FU70HY	FUSO SUPER GRATE	2018	1
	2PG-FV70HY	FUSO SUPER GRATE	2018-2019	4
	QKG-FU60VY	FUSO SUPER GRATE	2015	1
	QKG-FV50VY	FUSO SUPER GRATE	2013-2014	8
	QPG-FU60VY	FUSO SUPER GRATE	2017	1
	QPG-FV60VY	FUSO SUPER GRATE	2015-2016	11
UD TRUCKS	2PG-CD5BL	QUON	2019	3
	2PG-CW5BL	QUON	2018	4
	QKG-CW5YL	QUON	2013-2016	12
	QPG-CW5YL	QUON	2015	1
			TOTAL	143