

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4733	DATE	April 22 , 2020
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	In some detachable container vehicles, the gap between the fuel hose and the chassis frame supporter may not be enough because of an inadequate design of the chassis frame supporter. Therefore, due to the vibration during driving or the like, the fuel hose and the chassis frame supporter may touch, damage on the fuel hose, and lead to the fuel leakage in the worst case.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	2DG-FS1EJA	HINO PROFIA	2017-2019	17
	2KG-FS1EJA	HINO PROFIA	2018-2019	3
	2PG-FR1AJA	HINO PROFIA	2018-2019	5
	2PG-FS1AJA	HINO PROFIA	2017-2019	43
	2KG-FS1EHA	HINO PROFIA	2018	1
	2PG-FS1AHA	HINO PROFIA	2018-2019	5
	2PG-FS1EHA	HINO PROFIA	2017-2019	2
			TOTAL	76