

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ☒ Import Vehicles

CAMPAIGN No.	Gai-3024	DATE	2020/4/22
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class vehicles (463 platform) with 8-cylinder gasoline engine, the PA coating on the fuel line near the quickconnector might not meet the specification.</p> <p>In this case, fuel might creep underneath the PA coating, potentially leading to minor fuel sweating or drop formation at the quickconnector. Due to the installation position, contact of the leaking fuel with hot components can be excluded. In addition, the installation position favours rapid evaporation of minor leakages. Therefore, a risk of fire can be excluded.</p> <p>Furthermore, due to the small amount of fuel leaking, a risk of a crash for the following traffic can be excluded.</p> <p>However, local legal requirements regarding HC emissions might be exceeded.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-463260	G550	2019	68
ABA-463276	Mercedes-AMG G63	2019	118
		TOTAL	186