

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3025	DATE	2020/4/22
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class vehicles (463 platform), a fault in the engine software can result in a deviation of the mixture composition at high speeds and under high loads.</p> <p>This could lead to an excessive enrichment of the mixture in individual cylinders. In consequence misfires, which would be detected correctly, might occur. In case of too many misfires the affected cylinder would be deactivated for the current ignition cycle. The driver would be made aware of the issue by a flashing check engine light and noticeable engine jerking with simultaneous reduction of engine power.</p> <p>A negative impact on emissions cannot be excluded.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-463276	Mercedes-AMG G63	2019	1,051
		TOTAL	1,051