

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4740	DATE	May 14,2020
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	On the RH Rear Seat Belt, due to improper management of parts in the manufacturing process, the parts for the LH Seat Belt may be assembled. Therefore, the seat belt may not be operated correctly in the case of collision, and the occupant protection performance may be decreased.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5LA-GG3W	「OUTLANDER PHEV」	2019	507
DBA-GF7W	「OUTLANDER」	2019	55
DBA-GF8W		2019	96
		TOTAL	658