

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3035	DATE	May 27, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	In the mechatronics of 7 speed S-tronic automatic transmission, due to the Inappropriate threading of the upper housing, some are lacking in durability. As a result, due to continuous accumulation of hydraulic pressure change, the upper housing may be cracked, and in the worst case, the driving force cannot be transmitted and the vehicle cannot be driven, because of insufficient hydraulic pressure.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8JCDA	Audi TT Coupe 1.8	2012-2013	166
ABA-8PCAX	Audi A3 1.4TFSI	2009-2010	501
ABA-8PCDA	Audi A3 1.8	2009-2012	193
ABA-8XCTH	Audi A1 1.4/136kw	2014	1
DBA-8PCAX	Audi A3 1.4TFSI	2010-2013	1, 249
DBA-8VCPT	Audi A3 SB 1.4T 103kw	2014	2
DBA-8VCPTL	Audi A3 Sedan 103kw	2014	1
DBA-8VCXS	Audi A3 SB 1.4T 90kw	2014-2015	4
DBA-8XCAX	Audi A1 1.4/90kw	2011-2014	1, 316
		Total	3,433