

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	Gai-3036	DATE	May 28, 2020
MANUFACTURE	Automobiles PEUGEOT (Japanese Importer : Groupe PSA Japan Co.,Ltd.)		
DESCRIPTION OF DEFECT	Some vehicles were shipped without properly tightening the hose clamps at water hoses jointed to transmission oil cooler. As this result, cooling water may leak from the hose and warning light may lit. In the worst case, there is a risk of engine overheat due to insufficient cooling water.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-T9WYH01	308	2019	4
LDA-T9YH01			2
TOTAL			6