

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	gai-3032	DATE	Jun 1, 2020
MANUFACTURER	Hyundai Motor Company (Japanese importer : Hyundai Motor Japan Co., Ltd )		
DESCRIPTION OF DEFECT	The subject vehicles are equipped with an Anti-Lock Brake System ("ABS") module that remains powered on when the vehicle is turned off. It might be occurring the electrical circuit of the ABS module a short circuit internally then gradually increasing the risk of fire on the engine compartment.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-FD16	i30	2008. Jul ~ 2009. Oct.	32
ABA-FD20		2007. Sep. ~ 2008. Nov.	37
ABA-FDW16	i30CW	2009. May. ~ 2009. Jul.	18
ABA-FDW20		2009. Apr. ~ 2009. Jul.	11
		TOTAL	98