

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4754	DATE	June 4, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Passenger's airbag module may have an airbag that was sewn improperly, thereby lacking strength of the seams. When the airbag is activated in a collision, the seams can burst open, disabling the airbag from inflating completely whereby the occupant protective performance could be fallen off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-JH3	「N-WGN」	2019-2020	7,021
6BA-JH4	「N-WGN Custom」		1,597
		TOTAL	8,618