

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4755	DATE	June 4, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Rear seat belts may have a belt retractor locking mechanism which incorporates a spring that was bent as was assembled by an improperly adjusted assembling equipment. Such a bent spring can interfere with another component part of the locking mechanism whereby the retractor could fail to lock the seat belt when a sudden and quick pull came on the seat belt.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-RP1	「STEPWGN」	2019	104
DBA-RP2			36
DBA-RP3			2,270
DBA-RP4			440
6AA-RP5			1,136
DBA-GK3	「FIT」		2,464
DBA-GK4			313
DBA-GK5			141
DBA-GK6			5
DAA-GP5			318
DAA-GP6			82
DBA-RU1	「VEZEL」		374
DBA-RU2			46
DAA-RU3			552
DAA-RU4			69
DBA-FC1	「CIVIC」	40	
		TOTAL	8,390