

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3040	DATE	11, June, 2020
MANUFACTURER	Automobili Lamborghini SpA (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	It is possible that during the assembly, an operator may have not correctly engaged the bowden cable pin inside the internal door handles in a small limited number of vehicles. Over time the internal door handle mechanism may fail and the door cannot be unlocked from the inside, posing an entrapment risk. This failure could lead to the inability to operate the handles from inside the vehicle with a safety risk in case of emergency. The outside handles operation is guaranteed by a different component and its functionality is not affected. Therefore, it is still possible to open the doors normally from the outside.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-47L541	Aventador SVJ	2020	6
ABA-47L539	Aventador LP740-4	2020	1