

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3046	DATE	June 16th, 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the inline 3-cylinder diesel engine, the screwing of the camshaft bearing caps that fixed the camshafts to the camshaft carrier are insufficient due to a supplier fault. Therefore, the caps may loosen due to thermal loading or vibrations of the engine operation, the valves may not operate properly, and the engine could shut off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-XN15M	MINI Cooper D	2020	13
LDA-XT15M	MINI Cooper D 5 Door		55
		TOTAL	68