

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

|                       |   |      |               |
|-----------------------|---|------|---------------|
| CAMPAIGN No.          | Gai-3047  | DATE | June 16, 2020 |
| MANUFACTURER          | BMW (Japanese Importer: BMW Group Japan Corp.)  |      |               |
| DESCRIPTION OF DEFECT | The level of moisture within the propellant may have exceeded specifications during manufacturing. During deployment of the head airbag, the pressure inside the inflator could be larger than intended. The high pressure could cause the igniter to separate from the inflator and no or insufficient inflation of the airbag, which may injure the passengers. |      |               |

| TYPE     | COMMERCIAL NAME      | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|----------------------|---------------------|-------------------|
| LDA-JC20 | BMW 523d             | 2016-2017           | 20                |
| DBA-JA20 | BMW 530i             | 2016                | 9                 |
| DBA-JB30 | BMW 540i             | 2016                | 1                 |
| DBA-7A30 | BMW 740i             | 2016                | 98                |
| DLA-7D20 | BMW 740e iPerfomance | 2016                | 125               |
| CBA-7A44 | BMW 750i             | 2016                | 56                |
| TOTAL    |                      |                     | 309               |