

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4758	DATE	June 18 ,2020
MANUFACTURER	ISUZU MOTORS LIMITED		
DESCRIPTION OF DEFECT	Some rear bumper stays for servicing for medium duty trucks are not marked with an identification number, hence conformity with Safety Regulations for Road Vehicles, Article 18-2 (rear under-run protection device), cannot be confirmed.		

Vehicles Which Had The Affected Parts Installed After They Rolled Off The Assembly Line

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PA-FRD34L4	[FORWARD]	2004-2005	3
PA-FRD34M4		2004	1
PA-FRD34P4		2004	1
PB-FRD35J3S		2005	1
KK-FRD35L4		2001	1
KK-FRD35L4S		2004	1
PB-FRD35P3		2004-2005	2
KK-FRR33L4		2001-2003	2
PA-FRR34H4		2004	1
KK-FRR34L4 PA-FRR34L4		2003-2005	7
PA-FRR34M4		2004	1
KK-FRR35C3S PB-FRR35C3S		2002-2005	12
KK-FRR35C4S		1999-2003	10
PB-FRR35D3		2004	3
KK-FRR35D4		1999-2002	3
PB-FRR35E3S		2004	1
PB-FRR35H3S		2005	1
KK-FRR35H4		2006	1
KK-FRR35J3S PB-FRR35J3S		2004	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KK-FRR35J4S	[FORWARD]	2003-2004	4
KK-FRR35K3S		2000-2004	2
KK-FRR35K4		1999	1
KK-FRR35K4S		2000-2003	6
PB-FRR35L3		2004	2
KK-FRR35L3S		2003	1
KK-FRR35L4		1999-2004	7
KK-FRR35M4		2001	1
PKG-FRR90S1 PKG-FRR90S2 SKG-FRR90S1 SKG-FRR90S2 SKG-FRR90T2		2007-2012	97
ADG-FRR90C3S		2005-2007	35
ADG-FRR90D3		2007	1
ADG-FRR90K3S		2007	1
KK-NRR35C3 PB-NRR35C3		[FORWARD JUSTON]	2000-2005
KK-NRR35C4	2003		3
KK-NRR35G4	2003		1
		TOTAL	226

The Affected Parts Shipped As Repair Parts, But The Vehicles With Them Installed, Cannot Be Identified.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF VEHICLE
Rr Bumper Stay	1-71230440-2 1-71230441-2	2020	93
		TOTAL	93