VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3043	DATE	June 18, 2020
MANUFACTURE	Automobiles CITROEN (Japanese Importer :	Groupe PSA Japan Co., l	_td.)
DESCRIPTION OF DEFECT	On affected vehicles, there is a possibility that water goes through holes for tail gate rubber stop into inside body and finally enters into tail light due to insufficient evaluation of water proof of the rubber stop. This might cause malfunction of tail light by short circuit.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-B6HN01	C3	2017	1,206
	TOTAL		1,206