VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-3044	DATE	June 18, 2020
MANUFACTURE	Automobiles PEUGEOT		
	DS Automobiles		
	(Japanese Importer :	Groupe PSA Japan Co., I	_td.)
DESCRIPTION OF	On affected vehicles, s	strength of some rear	axle screws might be
DEFECT	insufficient due to not eno	ugh quenching. Screws	without enough strength
	might break and lead to a loss of trajectory of the vehicle.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-R85G06	508	2019	13
7BA-X745G06	DS 7	2019	1
	TOTAL		14