

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4763	DATE	Jun.24.2020
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the audio amplifier of the subject vehicles, due to an improper configuration of the circuits in the amplifier, an existing protective circuit does not operate properly if a short circuit occurs in specific circuits which are not made consideration to the influence of the debris contamination, leading to thermal damage in the amplifier circuit board. If this occurs, the combustible gas could create inside the amplifier, and in the worst case, vehicle fire could occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
DBA-GRS200	[CROWN]	2009-2010	277	equipped with Toyota premium sound system
DBA-GRS201		2009	23	
DBA-GRS202		2008-2012	1,204	
DBA-GRS203			401	
DBA-GRS204			2,966	
DAA-GWS204			3,966	
DBA-URS206	[CROWN MAJESTA]	2009-2013	5,072	
DBA-UZS207		1,091		
		TOTAL	15,000	