

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4760	DATE	June 25 , 2020
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>Due to the improper program in ISG (Integrated Starter Generator) self diagnosis system, ISG could misjudge the raise of the electric resistance by the oxide layer formed in the earth terminal in normal usage of the vehicle, as the ISG circuit failure.</p> <p>In case of above, ISG stops the generation of electricity and turns on the warning light.</p> <p>If the vehicle is being used continuously in such condition, the lead-acid battery may discharge and the engine may stall or fail to start.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-MH44S	WAGON R	2014～2015	69,226
DAA-MK42S	SPACIA	2015	23,431
DAA-MR41S	HUSTLER		22,867
DAA-MJ44S	FLAIR	2014～2015	5,118
DAA-MM42S	FLAIR WAGON	2015	2,265
DAA-MS41S	FLAIR CROSSOVER		1,595
		TOTAL	124,502