

## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	4766	DATE	June 26, 2020
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	In the differential case of a load stabilizer, hydraulic oil may leak due to head pressure into the case due to improper hydraulic control of hydraulic oil. Therefore, if you continue to use the machine as it is, the hydraulic oil may leak from the gear case air breather.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
1PM5	「PM550」	2008 – 2019	52
TOTAL			52