

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~-Vehicles

CAMPAIGN No.	4768	DATE	June 26, 2020
MANUFACTURE	SUMITOMO NACCO FORKLIFT CO., LTD. (Japan)		
DESCRIPTION OF DEFECT	Transistor capacity in the controller for running is insufficient and there are variations for applying the thermal grease, so that the current is concentrated on some transistors, and it causes high temperature. Therefore, if the trucks continue to be used as it is, the transistor may be damaged and the current to the traction motor may be cut off, then the trucks may not run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-SB2L	FB20PSXIII FB25PSXIII	2016 ~ 2018	44
		TOTAL	44