

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3051	DATE	June 30, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	Some vehicles have a narrow gap between the fuel tank and a bracket fitted on the vehicle body due to manufacturing tolerances. As a result, the fuel tank is collided with the bracket and damaged in the event of an accident, and in the worst case, the fuel is leaked from the tank.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-FVCHHF	Audi TT 2.0Tq / Audi TT 45Tq	2016-2019	2,546
ABA-FVCJXF	Audi TTS	2016-2019	817
ABA-FVDAZF	Audi TTRS	2017-2018	291
		Total	3,654