

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3055	DATE	June 30 <sup>th</sup> , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The recall involves the steering gear tie rods of an earlier design configuration. There is a risk that the tie rods' kink groove experience damage under influence of vibrations loads from the road surface and very high temperature conditions. In the worst case, steering control may not be possible.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-5F20	BMW 320i	2018 – 2020	2,403
3BA-5F20	BMW 330i	2018 - 2019	656
3DA-5V20	BMW 320d xDrive	2019	252
3BA-TS30	BMW X3 M	2019	2
3BA-TS30	BMW X4 M	2019	2
3BA-HF30	BMW Z4 M40i	2018 - 2019	137
3BA-HF20	BMW Z4 sDrive 20i	2018 - 2019	303
TOTAL			3,755