

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3053	Date	Jul 2, 2020
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to improper process control of the fuel hose during a limited production, poor durability fuel hose may have been manufactured and installed on the fuel hose. As a result, the fuel hose deteriorates early, and in the worst case, fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-5NDFGF	Tiguan TDI / 110kW	MY2020	152
3DA-AUDFG	Golf TDI / 110kW	MY2020	50
	Golf Variant TDI / 110kW	MY2020	38
LDA-1TDFG	Golf Touran TDI / 110kW	MY2020	49
3DA-7NDLU	Sharan TDI / 130kW	MY2020	113
Total			402