

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4775	DATE	Jul. 7 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty buses, a DPF muffler with specifications for a different model is installed incorrectly due to inappropriate checking after installation work of the DPF muffler. As a result, the vehicle may not comply with Article 31 of the Safety Standards (emission standards).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-BE740E	「FUSO ROSA」	2019~2019	3
2RG-BE740G		2019~2019	37
2RG-BE740J		2019	1
2RG-BG740G		2019~2019	6
		TOTAL	47