

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3057	DATE	2020/7/16
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain S-Class (222 platform) and S-Class Coupe/Convertible (217 platform) vehicles with 4.0l 8-cylinder gasoline-engine the material of two closure plugs on the engine might not withstand the maximum loads while driving.</p> <p>Thus, the material of the closure plugs might fail as a result of high engine oil pressures, which occur especially during dynamic driving. It cannot be ruled out that engine oil leaks from the plugs. Leaking oil might get onto the road, increasing the risk of a crash for the following traffic. If the engine oil level were to fall below a certain limit, the driver would be made aware of this issue by a red warning message in the instrument cluster.</p> <p>If the warning message were to be ignored by the driver, the engine could run dry. In this case, a stalling of the vehicle cannot be ruled out due to an engine damage.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
DBA-222183	S560	2018	730	
		2019	62	
DBA-222183C		2018	50	
		2019	3	
DBA-222186		S560 4MATIC	2018	964
			2019	49
DBA-217383C	S560 Coupe	2018	39	
		2019	2	
DBA-217386	S560 4MATIC Coupe	2018	40	
		2019	7	
DBA-217483	S560 Cabriolet	2018	23	
		2019	5	
DBA-222983C	Mercedes Maybach S560	2018	60	
		2019	13	
DBA-222986	Mercedes Maybach S560 4MATIC	2018	63	
		2019	5	
		TOTAL	2,115	