

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	gai-3045	DATE	Jul 17 , 2020
MANUFACTURER	Hyundai Motor Company (Japanese importer : Hyundai Motor Japan Co., Ltd)		
DESCRIPTION OF DEFECT	The target vehicle may has a clutch booster fixing bolt that is longer than the normal bolt due to improper manufacturing process control. Therefore, the clutch booster is not properly fixed, the fixing plate may be damaged by vibration, and then it might occur the clutch booster drop off then the vehicle unable to run in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
LDG-RD00	UNIVERSE	2015. Jan ~ 2017. Jul.	329
		TOTAL	329