

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	4781	DATE	13th July 2020
MANUFACTURER	NISSAN		
DESCRIPTION OF DEFECT	<p>Possibility that there is insufficient clearance between seat bolts and fuel tank.                  If condition exists, it may cause to dent the fuel tank with a bolt.                  Correct by inspecting and replacing bolts and fuel tank if necessary.</p>		

TYPE	COMMERCIAL NAME	MODELYEAR RECALLED	NUMBER OF VEHICLE
CBF-VNM20	NV200 VANETTE (GMLVAN C-01)	22th December 2018~7th May 2020	VNM20-101475 ~VNM20-107544
TOTAL			