

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3042	DATE	20 July, 2020
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to a wrong material combination at the supplier, there is the possibility, that the friction welding between the line and the flange of an ATF oil line for the automatic transmission does not meet the required specifications. If this is the case, there might be a fluid leakage between the line and the flange. If a transmission fluid leak occurs while driving, the road may become slippery, which may lead to a risk for the following traffic.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-E3K30	Cayenne	2020	131
ABA-E3K30A			39
		Total	170