

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 3041	DATE	27 July, 2020
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	the tightness of the quick connector of the fuel supply line possibly may not be ensured due to a component weakness at very high temperatures in the engine compartment. This can lead to a fuel leakage at the quick connector of the fuel supply line, which may be perceived by smell of fuel.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-E3K40A	Cayenne Turbo	2019	300
		2020	79
3LA-E3L40A	Cayenne Turbo S	2020	23
		Total	402