

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4765	DATE	July 28, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	<p>In the electric power steering of an electric forklift truck, due to improper setting of steering assist, strong inertial collision force which exceeds the material strength of the rear axle could be generated when the steering wheel is turned to the end.</p> <p>Therefore, if it is continuously used in the state, the rear axle may be damaged and the steering may not be operated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
251AC	「TRANSER」	2007～2013	9
		TOTAL	9