

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4786	DATE	July 28 , 2020
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding some of the van type refrigerated/freezer trucks, strength of the joint between the body rail and the side panel is insufficient because of inappropriate construction management. Therefore, there is a possibility that the cracks may occur on said joint due to the burden at the time of running, and the body rail may be peeled off. And in the worst case, it may not be able to continue to run because the body rail will break and it may hit the tire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CD5CA	QUON	2017~2019	91
2PG-CD5CE	QUON	2019	1
2PG-CG5CA	QUON	2018~2019	14
2PG-CW5CA	QUON	2018~2019	2
QPG-CD5ZA	QUON	2017	1
2PG-CYJ77C	GIGA	2018~2019	12
2PG-CYL77C	GIGA	2017~2018	3
2PG-CYY77C	GIGA	2018	1
2PG-FS74HZ	FUSO SUPER GREAT	2018~2019	5
2PG-FU74HZ	FUSO SUPER GREAT	2017~2019	21
2PG-FU75HZ	FUSO SUPER GREAT	2018~2019	5
2PG-FR1AHG	HINO PROFIA	2017	1
2PG-FR1AHH	HINO PROFIA	2019~2020	3
2PG-FR1EHG	HINO PROFIA	2018~2019	13
2PG-FR1EHJ	HINO PROFIA	2019	1
2PG-FS1EHG	HINO PROFIA	2019	1
2PG-FW1AHG	HINO PROFIA	2018~2019	7
2PG-FW1AHJ	HINO PROFIA	2018~2019	17
2RG-FR1AHG	HINO PROFIA	2018~2019	9
2RG-FR1AHJ	HINO PROFIA	2019	2
2RG-FW1AHG	HINO PROFIA	2019	1
2RG-FW1AHJ	HINO PROFIA	2018	1
2SG-FR1AHH	HINO PROFIA	2019	1
		TOTAL	213