

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4784	DATE	Jul. 30 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty tractors equipped with a 400 liter aluminum fuel tank, the strength of the fuel tank is insufficient, and cracks may occur in the welds of the tank due to vibration during traveling. If the vehicle continues to be used in this condition, the cracks may progress and fuel may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FP74GGR	「FUSO SUPER GREAT」	2018~2019	2
2RG-FP74HDR		2017~2019	1,220
2RG-FP74HER		2017~2019	479
2RG-FP74HGR		2017~2019	51
		TOTAL	1,752