

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4788	DATE	July.30 2020
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty touring buses, the durability of the heater hose is insufficient, so the heater hose may be damaged early. If the hose is damaged, coolant may leak. Continued use of the vehicle may result in overheating.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2017~2020	1,693
	「FUSO AERO QUEEN」	2017~2020	308
		TOTAL	2,001