

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic)/ Import Vehicles

CAMPAIGN No.	4795	DATE	Aug. 24. 2020
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain pistons of engines, due to improper equipment conditions in the casting process, the strength of the piston ring groove part may be insufficient. Therefore, cracks may be generated in the groove, resulting in damage of the engine while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FC6JCWA	[HINO Ranger]	2010～2011	363
BDG-FC6JDWA		2010～2011	18
BDG-FC6JEWA		2010～2011	85
BDG-FC6JGWA		2010～2011	87
BDG-FC6JHWA		2010～2011	3
BDG-FC6JJWA		2010～2011	139
BDG-FC6JKWA		2010～2011	215
BDG-FC6JLWA		2010～2011	151
BDG-FC7JCWA		2010～2011	47
BKG-FC7JCYA		2010～2011	1,620
BDG-FC7JDWA		2010～2011	59
BDG-FC7JEWA		2010～2011	41
BKG-FC7JEYA		2010～2011	170
BDG-FC7JGWA		2010～2011	6
BDG-FC7JGWG			
BKG-FC7JGYA		2010～2011	145
BKG-FC7JGYG			
BDG-FC7JHWA		2011	2
BKG-FC7JHYA		2010～2011	161
BKG-FC7JHYG			
BDG-FC7JJWA		2010～2011	8
BDG-FC7JJWG			
BKG-FC7JJYA		2010～2011	586
BKG-FC7JJYG			
BDG-FC7JKWA		2010～2011	9
BDG-FC7JKWG			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-FC7JKYA	[HINO Ranger]	2010～2011	1,571
BKG-FC7JKYG		2010～2011	98
BKG-FC7JLYA		2010～2011	2
BKG-FC7JLYG		2010～2011	64
BDG-FC7JNWA		2010～2011	10
BKG-FC7JNYA		2010～2011	5
BKG-FC7JNYG		2010～2011	28
BKG-FC7JSYA		2010～2011	57
BKG-FC7JWYA		2010～2011	85
BKG-FC7JWYG		2010～2011	100
BDG-FD7JDWA		2010～2011	135
BKG-FD7JDYA		2010～2011	3
BDG-FD7JEWKA		2010～2011	99
BDG-FD7JGWA		2010～2011	1
BKG-FD7JGYA		2010～2011	223
BDG-FD7JJWA		2010～2011	16
BDG-FD7JJWG		2010～2011	1,658
BKG-FD7JJYA		2010～2011	107
BKG-FD7JJYG		2010～2011	1
BDG-FD7JKWA		2010～2011	129
BKG-FD7JKYA		2010～2011	3
BKG-FD7JKYG		2010～2011	16
BDG-FD7JPWA		2010～2011	4
BKG-FD7JPYA			
BKG-FD7JPYG			
BDG-FD7JUWA			
BKG-FD7JUYA			
BKG-FD7JWYA			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FD8JGWA	[HINO Ranger]	2010～2011	25
BDG-FD8JGWG		2010～2011	46
BDG-FD8JJWA		2010～2011	146
BDG-FD8JJWG		2010～2011	1,001
BDG-FD8JKWA		2010～2011	130
BDG-FD8JKWG		2010～2011	105
BDG-FD8JKWJ		2010～2011	8
BDG-FD8JMWA		2010	4
BDG-FD8JMWG		2010	1
BDG-FD8JMWJ		2010	1
BDG-FD8JPWA		2010	1
BDG-FD8JPWG		2010	2
BDG-FD8JUWA		2010	1
BDG-FD8JUWG		2010	3
BDG-FD8JWWA		2010	1
BDG-FE7JEWA		2010	2
BDG-FE7JGWA		2010	3
BDG-FE7JJWA		2010	9
BDG-FE7JKWA		2010	7
BDG-FE7JLWA		2010	8
BDG-FE7JMWA		2010	2
BDG-FE7JPWA		2010	1
BDG-FE7JPWG		2010	3
BDG-FE8JGWA		2010	1
BDG-FE8JJWA		2010	2
BDG-FE8JKWG		2010	3
BDG-FE8JLWA		2010	9
BDG-FE8JLWG		2010	2
BDG-FE8JMWA		2010	7
BDG-FE8JMWG		2010	8
BDG-FE8JPWA		2010	2
BDG-FE8JPWG		2010	1
BDG-FG8JKWA		2010	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FG8JMWA	[HINO Ranger]	2010	1
BDG-FJ7JDWA		2010	7
BDG-FJ7JGWA		2010	1
BDG-FJ7JHWA		2010	2
BDG-FJ7JJWA		2010	2
BDG-FJ7JKWA		2010	6
BDG-FJ7JKWG		2010	2
BDG-FJ7JLWA		2010	1
BDG-FJ7JLWG		2010~2011	7
BDG-FJ7JSWA		2010	1
BDG-FT8JGWL		2010~2011	13
BDG-FT8JHWL		2010	1
BDG-FX7JDWA		2010~2011	20
BDG-FX7JGWA		2010~2011	8
BDG-FX7JJWA		2010~2011	13
BDG-FX7JLWA		2010~2011	13
BDG-GC7JDWA		2010~2011	9
BKG-GC7JDYA	[HINO Ranger]	2010~2011	13
BKG-GC7JEWA		2010~2011	15
BKG-GC7JEYA		2010~2011	23
BKG-GC7JGYA		2010~2011	34
BKG-GC7JHYA		2010~2011	4
BKG-GC7JHYG		2010~2011	11
BKG-GC7JJYA		2010~2011	35
BKG-GC7JJYG		2010~2011	32
BKG-GC7JKYA		2010~2011	5
BKG-GC7JKYB		2010~2011	1
BKG-GC7JKYG		2010~2011	9
BKG-GC7JLYA		2010~2011	57
BKG-GC7JLYG		2010~2011	31
BKG-GC7JNYA		2010~2011	23
BKG-GC7JSYA		2011	
BKG-GD7JEYA		2010~2011	
BDG-GD7JGWA		2010~2011	
BKG-GD7JGYA		2010~2011	
BKG-GD7JJYA		2010~2011	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BKG-GD7JKYA	[HINO Ranger]	2010～2011	32
BKG-GD7JLYA		2010～2011	43
BKG-GD7JLYB			
BKG-GD7JLYG			
BKG-GD7JMYA		2010～2011	16
BKG-GD7JMYG			
BKG-GD7JPYA		2010～2011	10
BDG-GD8JGWA		2010	2
BDG-GD8JJWA		2010～2011	10
BDG-GD8JJWG			
BDG-GD8JKWA		2010～2011	8
BDG-GD8JKWG			
BDG-GD8JLWA		2010～2011	30
BDG-GD8JLWB			
BDG-GD8JLWG			
BDG-GD8JMWA		2010～2011	13
BDG-GD8JMWG			
BDG-GD8JPWA		2010～2011	26
BDG-GD8JPWG			
BDG-GD8JUWA		2010～2011	3
BDG-GK8JKWA		2010	6
BDG-GK8JLWA		2010	1
BDG-GK8JNWA		2010	1
BDG-GK8JRWA		2010	5
BDG-GK8JWWA		2010	3
BDG-GX7JDWA		2010	4
BDG-GX7JGWA		2010～2011	161
BDG-GX7JKWA		2010～2011	5
BDG-GX7JLWA		2010～2011	3
		TOTAL	10,741

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-FC6JCFA	[HINO Ranger]	2004	2

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-FC6JCWA	[HINO Ranger]	2005~2008	6
BDG-FC6JCWA			
PB-FC6JDFA		2005	1
ADG-FC6JDWA		2005	1
ADG-FC6JEWA		2006~2007	2
BDG-FC6JEWA			
ADG-FC6JGWA		2006~2007	3
BDG-FC6JGWA			
ADG-FC6JJWA		2005~2007	5
BDG-FC6JJWA			
ADG-FC6JKWA		2005~2008	7
BDG-FC6JKWA			
ADG-FC6JLWA		2006	1
PB-FD7JKFA		2004~2005	4
PB-FD7JKFG			
ADG-FD7JKWA		2006	2
PB-FD7JLFA		2003~2005	12
ADG-FD7JLWA		2005~2007	10
ADG-FD7JLWJ			
BDG-FD7JLWA			
BDG-FD7JLWG			
PB-FD7JMFA		2005	1
PB-FD7JPFA		2004~2005	2
PB-FD7JPFG			
BDG-FD8JJWA		2007	1
PB-FD8JKFA		2004	1
PB-FD8JLFA		2004~2005	7
PB-FD8JLFG			
BDG-FD8JLWA		2007~2008	4
BDG-FD8JLWG			
BDG-FD8JMWA		2006~2007	2
BDG-FD8JMWG			
PB-FD8JPFG		2005	1
ADG-FD8JPWA		2006	1
ADG-FE7JEWA		2005	1
PK-FE7JGFA		2005	1
KS-FE7JLFA		2005	1
ADG-FE7JLWA		2005~2007	4
BDG-FE7JLWA			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KS-FE7JPFA	[HINO Ranger]	2005	1
ADG-FE8JUWA		2006	1
ADG-FG8JJWA		2006	1
KS-FJ7JEFA		2004	1
PB-GC7JGFA		2005	1
PB-GD7JLFA		2004	3
BDG-GD7JLWA		2007	1
KS-GK8JKFA		2005	2
ADG-GK8JKWA		2006	4
BDG-GK8JLWA		2007	1
ADG-GK8JNWA		2005～2007	5
BDG-GK8JNWA			
KS-GK8JWVA		2004	1
BDG-GK8JWWA		2007	1
ADG-GK8JWXA		2005～2008	6
BDG-GK8JWXA			
	TOTAL		112