

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3079	DATE	August 26, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	For the mechatronics of 7 speed S-tronic automatic transmission, due to the inappropriate housing processing accuracy of the accumulator mounting part, in some cases, a small crack occurred in the housing a large hydraulic pressure fluctuation such as during start-up or traffic jam. As a result, when the hydraulic pressure decreases, the warning light is turned on, the worst case the driving force cannot be transmitted and the vehicle cannot be driven.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8JCDA	Audi TT Coupe 1.8T	2012-2013	817
ABA-8PCDA	Audi A3 1.8T	2011-2012	71
DBA-8PCAX	Audi A3 1.4TFSI	2011-2013	4,653
DBA-8XCAX	Audi A1 1.4/90kw	2011-2013	5,474
		Total	11,015