

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4793	DATE	Aug.27, 2020
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the HID specification headlamps (headlights for passing), due to the combination of the bulb and the reflection surface specification, deterioration of the reflection surface is promoted by UV rays from the bulb. Therefore, if continue to use, the aluminum vapor deposition on the reflecting surface is exfoliated and the luminous intensity is gradually reduced. In the worst case, it may not comply to the Japanese Safety Regulations for Road Vehicles prescribed in Article 32 (headlight standard).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	「LEGACY」	2009 ~ 2013	14,737
DBA-BMG		2012 ~ 2014	2,506
DBA-BMM		2012 ~ 2014	7,329
DBA-BR9		2009 ~ 2013	53,693
DBA-BRF		2009 ~ 2014	1,814
DBA-BRG		2012 ~ 2014	7,963
DBA-BRM		2012 ~ 2014	28,498
			TOTAL