

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-3074	DATE	2020/8/27
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain V-Class (639 platform) vehicles, the legal requirements in Japan regarding tightness of the complete tank system of your vehicle might not be met in all circumstances in the area of the fuel pump. In case of long-term mechanical stress onto the return nozzle of the fuel pump, small fuel amounts might leak on top of the fuel tank. Since this area is not close to any potential source of ignition, such as components with a hot surface, a potential risk of fire can be ruled out.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-639811	Viano	2004	2,687
ZZ-639603		2006	1
GH-639811C	Viano3.2	2004	1,238
ABA-639811	V350	2007	636
ABA-639350		2008	1,166
ABA-639350A		2011	594
ABA-639811C		2007	474
ABA-639350C		2007	608
ABA-639350C		2008	1,112
ABA-639350T		2011	627
-639350-			691
-639350C-			1
-639350C-			1
		TOTAL	9,836