

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3075	DATE	2020/8/27
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain A-Class vehicles (177 platform) the air conditioning drain hose might be installed incorrectly. In this case, condensation water from the air conditioning might enter the passenger compartment.</p> <p>The condensation water might enter into the driver and passenger side footwells as well as on the center tunnel, potentially causing corrosion and/or short circuits to the electrical components installed in this area.</p> <p>This might lead to different consequences, among others the SRS control unit might malfunction, the vehicle might not start, the engine limp-home mode might be activated during driving and the performance of further features (e.g. fuel pump, automatic/manual emergency call) might be impaired. This would increase the potential risk of injury or a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	A 180	2019	4
5BA-177084M			521
5BA-177084			4,016
5BA-177184	A 180 Sedan		1
3DA-177012	A220d		3
		TOTAL	4,545