

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3076	DATE	2020/8/27
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class vehicles (463 platform) the control unit of the differential locking module might not meet the specification. The electrical contact of a specific resistor might be impaired due to sulfur fumes originating from the axle oil.</p> <p>If the resistor is impaired, the electrical currents calculated with this resistor would have been recognized as too high. In consequence, the communication between the control unit and the locking actuator will be shut down. In this case, the differential locking status could not be reliably determined. According to the specified system strategy for locked differentials, both ESP and ABS systems would be deactivated. This could increase the risk of a crash under certain operating conditions.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-463349	G350d	2019	1,112
		2020	21
ABA-463260	G550	2019	544
3BA-463260		2020	1
ABA-463276	Mercedes-AMG G63	2019	2,161
		2020	31
		TOTAL	3,870