

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4801	DATE	August 28, 2020
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Engine oil pan may not be suitably coated whereby its mounting bolts can come loose under the influence of heat from the running engine and eventually engine oil can leak out of the oil pan and, in the very worst case, leaked oil could stick to the rear tire, causing the vehicle to fall over.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BK-MC51	「CBR250RR」	2017-2020	11, 500
		TOTAL	11, 500