

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	4799	DATE	August 31, 2020
MANUFACTURER	Mitsubishi Logisnext Co., Ltd		
DESCRIPTION OF DEFECT	Due to improper assembling of the accelerator which controls truck speed of a fixed platform truck, accelerator malfunction can occur while operating the accelerator lever and the truck may continue to move without slowing down even if the operator releases the accelerator lever.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
471AB	「ELETRUCK」	2018 2019	120
		TOTAL	120