

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-3086	DATE	Aug 31 2020
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd. )		
DESCRIPTION OF DEFECT	The windshield wipers may have been built with an improperly formed wiper arm head joint that did not fully form the splines of the head joint on the wiper arm. This can allow the joint to strip and result in the wiper arm failing to operate properly when the system is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-M624	「Compass」	2020	148
		TOTAL	148