

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3087	DATE	September 2 <sup>nd</sup> , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	This recall involves the third break lamp at the rear end of the roof. Due to inappropriate setting of attachment equipment, the screw connections may lose their preload force and rattle. Under dynamic stimulation while driving, the lamp could detach from the vehicle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-6C44M	BMW M6 Gran Coupe	2013 - 2017	364
		TOTAL	364