

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3088	DATE	September 2 nd , 2020
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The outer shell of the rear spoiler on the roof of affected vehicles has been insufficiently bonded. This is due to incorrect setting of parameters of adhesive proportioning system at supplier's production process. Therefore, the adhesive strength in concerned sectors may be reduced due to vehicle vibration. In worst case, the rear spoiler on the roof may detach from a moving vehicle and become a hazard to other road users.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7DA-GT30	BMW X6 xDrive 35d	2019	12
		TOTAL	12