

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3085	DATE	September 3, 2020
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	A nozzle used to direct the gas from the inflator into the curtain airbag cushion was not adequately welded due to improper production. As a result, the nozzle may be fail and the gas may not be adequately directed into the cushion to enable a complete deployment of the airbag in the event of the curtain airbag is triggered, and in the worst case, the occupant protection is restricted.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-4MCREA	Audi Q7 55Tq Air suspension	2019	5
ABA-4MCYRA	Audi Q7 45Tq Air suspension	2019	3
		Total	8