

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-3095	DATE	September 14, 2020
MANUFACTURER	ALPINA Brukard Bovensiepen GmbH + Co. KG (Japanese Importer: Nicole Racing Japan LLC)		
DESCRIPTION OF DEFECT	The fuel tank may have a welding fault on the lid of the mounting hole for the suction jet pump. Due to driving vibration etc., this may lead to the formation of cracks at the weld seam, where the fuel may leak from.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3R20	B3 Biturbo	2013 - 2015	201
	B3 Biturbo Touring	2013 - 2015	51
	B4 Biturbo Coupe	2014 - 2015	65
ABA-4R20	B4 Biturbo Cabrio	2014 - 2015	21
ABA-3R30	B3 Biturbo	2016	69
	B3 Biturbo Touring	2016	23
	B4 Biturbo Coupe	2015 - 2016	31
	B4 Biturbo Cabrio	2016	11
		TOTAL	472